

Government of India Office of the Chief Engineer (SZ) I CPWD, Rajaji Bhavan Besant Nagar Chennai 600 090

No CE/ SZ I / Cost Index/ 2014/ 3111-14

E---

Date: 17.06.2014

Sub: Revision of Cost Index as on 01/04/2014, Repair and Service Cost Indices, as on 01.04 2014 for Pondicherry, Karaikal & Port Blair-A & N Islands.

The Chief Engineer (SZ) I, CPWD, Chennai, has approved the Cost Indices as on **01.04.2014** for Pondicherry, Karaikal and Port Blair as detailed below over the base of 100 as on 01.10.2012.

S No	Name of Place	State	Coat Index as on 01.04.2014	Remarks
		Puducherry	110	1
1	Pondicherry	Puducherry	111	
2	Karaikal	A & N	120	
3	PORT BLAIR	AXIV		
L	Repair Cost index for	Puducherry	1641	
	Pondicherry.	Tamilnadu	1641	
2	Repair Cost index for Cuddalore		2046	
3	Service Cost index for	Puducherry	2046	
	Pondicherry.	Tamilnadu	2046	
4	Service Cost index for Cuddalore	Taitiillauu	1020	
5	Repair Cost index for Port	A & N	1828	
2	Blair	ISLANDS A & N	2114	
	Service Cost index for Port			

(L.BADHRACHALAM) Superintending Engineer (P)

Copy communicated to:

- The ADG (SSR) I, CPWD, Rajaji Bhavan. Chennai-600 090, with a request to upload in the website please.
- The Chief Engineer (CSQ) Civil, CPWD, Nirman Bhavan, A wing, New Delhi-11.
- 3. The Chief Engineer (Electrical), CPWD, Chennai -600 090.
- 4. The Chief Engineer (VAL), Income tax Department Chennai.
- 5. The Superintending Engineer (E).CCEC I, CPWD, Chennai-600 006.
- 6. The Superintending Engineer CCC I & CCC II, CPWD, Chennai-600 006.
- 7. The Executive Engineer, PCD, CPWD, Puducherry.
- 8. The Executive Engineer, PCED, CPWD, Puducherry.
- 9. The Executive Engineer, KPD, CPWD, KARAIKAL.
- 10. The Executive Engineer, ACD, CPWD, PORT BLAIR.
- 11. The Executive Engineer, CCED-III, CPWD, Chennai.
- 12. The Executive Engineer, (VAL), Income tax Department Chennai,

13. Construction Reporter, 94/B-6, Sector-7, Rohini, New Delhi.

14. The DDG (HR) with a request to upload in the web site.

Superintending Engineer (P)

106/14